Technical

Data Sheet



Willamette Valley Company www.wilvaco.com **800.333.9826**

Partnering through service, innovation, and integrity



www.WVCORAILROAD.com

SALES DESK 1-800-333-9826 sales@wvcorailroad.com

SPIKEFAST® CTR-100

Concrete Railseat Repair Material

DESCRIPTION

SPIKEFAST® CTR-100 is specifically designed to remediate railseats on concrete ties. This durable, 100% solids polyurethane is designed to adhere, seal, and extend the service life of a railseat. CTR-100 is dispensed from equipment engineered for efficient metering/mixing, presssure and temperature control. CTR-100 can be applied in a wide range of outdoor conditions.

WHERE TO USE

- Concrete Railseats—repair worn and abraded railseats
- Sealing Concrete Surfaces—fill cracks and defects
- Beneath Tie Pad-adhere pad to railseat

FEATURES AND BENEFITS

- Quick Cure Times—high production rates
- Restore Original Geometry—proper cant and gauge
- Reduced Head Deflection—greater longitudinal rail restraint
- Third-Party Cycle Tested—passed over 3-million cycles

PACKAGING

COLORDark Orange

200-gallon totes (758 L)

50-gallon drums (190 L)

5-gallon buckets (19 L),

15-oz. cartridges (450 ml)

YIELD

38 Railseats (45 in 2 x 0.125 in.) per gallon.

11 Railseats (290 cm² x 0.32 cm) per liter.

SHELF LIFE

6 months in containers and 12 months for cartridges when properly stored.

STORAGE

Store in original container and sealed until ready for use. Reseal used containers and store in an upright position.

TECHNICAL INFORMATION

Typical Properties

VOC, lbs/gal (g/L), ASTM D 2369	0
Viscosity, cps, ASTM D 4878, Resin / Iso	3300 / 200
Hardness, Shore D, ASTM D 2240	80
Set time, sec, 70°F (20°C)	60 or 120 seconds – Bulk Containers 120 seconds - Cartridges (Temperature dependent)
Service temperature, ° F (° C)	-40 to 180 (-40 to 82)

Processing Parameters

Ratio by volume, Resin to Iso	2 to 1
Meter equipment	Plural component
Static mixer	13-32 bulk, 13-24 cartridge
Typical application volume, in ³ (cm ³)	5.6 in ³ (92 cm ³)

APPLICATION

SPIKEFAST® is supplied in a ready-to-use form that requires proper mixing and dispensing. Care should be taken that SPIKEFAST® is stored properly, does not become contaminated with foreign matter, and is applied according to WVCO recommendations.

METER DISPENSED

PROCESSING

For meter applied applications contact Willamette Valley Company Precision Technologies Division for equipment recommendations. Willamette Valley Company's metering equipment is specifically engineered for processing SPIKEFAST® to generate the proper mix ratio, pressure, and temperature.

- 1. Test the meter operation before dispensing onto railseat/tie defect.
- 2. Place mix-tube on nozzle and tighten retaining nut over the mix-tube. Use a 13-mm diameter mixer with 32-elements.
- 3. Dispense in test container to verify CTR-100 material sets up uniformly in less than 4-minutes.

APPI ICATION

- 1. Dispense CTR-100 onto the railseat/tie defect.
- Fill railseat/tie defect from one side to the other in a uniform motion. Avoid over filling.
- 3. Top off railseat/defect as necessary.
- Flush mix-tube as necessary if dispensing stops. Dispense mix-tube flush outside the railseat/tie defect when resuming tie remediation.
- Material may solidify in the mix-tube if application stops for more than 20-30 seconds. Remove spent mix-tube and replace with a new mixtube as necessary.
- Periodically inspect applied material to ensure the material is solidifying and uniform. If material is non-uniform; stop, change mix tube and check meter operation for compliance.

NOTE: Material will set in approximately 60 seconds at $70^{\circ}F$ (21°C). Colder temperatures will slow the set. Warmer temperatures will speed the set.

CARTRIDGE DISPENSED

PROCESSING

- For colder conditions it is recommended to put the product in a warm area at approximately 70°F (21°C) for 24 hours before using. This will enhance the flow and cure time.
- $2. \quad \text{Use a 13-mm diameter with 24-element static mix tube}.$

CARTRIDGE APPLICATION

- Use a 2:1 (resin:iso) hand applied dispenser and ensure that the dispenser is the proper size and type. Manual, cordless, and pneumatic applicator guns all work adequately. Pneumatic and cordless applicators provide the most consistent results.
- 2. Keep the cartridge upright during assembly.
- 3. Remove the retaining nut and caps from the cartridge.
- 4. Place mix-tube on cartridge nozzle and hand tighten the retaining nut over the mix-tube.
- 5. Check alignment of plungers inside cartridge; level if necessary.
- 6. Keep cartridge upright and load into applicator gun.
- While pointing cartridge upright, trigger handle to remove any air trapped in cartridges.
- Point cartridge over waste container and dispense initial amount of material (20-40mL).
- Fill railseat/tie defect from one side to the other in a uniform motion. Avoid over filling.
- 10. Top off railseat/tie defect as necessary.
- Material may solidify in the mix-tube if application stops for more than 20-30 seconds. Remove spent mix-tube and replace with a new tube to finish cartridge.

Contact a Willamette Valley Company Representative for more information on product and equipment instructions, recommendations, and full-service warranty.

HEALTH AND SAFETY

Before handling, you should become familiar with the Material Safety Data Sheet (MSDS) regarding the risks and safe use of this product. To obtain an MSDS please call 800 333 9826 or send an email to: msds@wilvaco.com..

WILLAMETTE VALLEY COMPANY

www.wilvaco.com info@wilvaco.com

DIVISIONS

WESTERN DIVISION

1075 Arrowsmith Street PO Box 2280 Eugene, OR 97402 Tel 541.484.9621 www.POLYQUIK.com www.WVCORAILROAD.com

EASTERN DIVISION

6662 Marbut Road Lithonia, GA 30058 Tel 888.878.9826

MIDWEST DIVISION

1549 Hwy 2 Two Harbors, MN 55616 Tel 218.834.3922

PRECISION TECHNOLOGIES DIVISION

675 McKinley Street Eugene, OR 97402 Tel 541.484.2368 www.pre-tec.com

SOUTHERN DIVISION

100 Dixie Mae Drive PO Box 4450 Pineville, Louisiana 71361 Tel 318.640.5077

SUBSIDIARIES

CANADIAN WILLAMETTE

19081- 27th Avenue Surrey BC V3S 5T1 Tel. 800.663.4298

ECLECTIC PRODUCTS INC.

Corporate Office 1075 Arrowsmith Street Eugene, OR 97402 Tel 541.284.4667 www.eclecticproducts.com

IDAHO MILL & GRAIN

445 North 430 West Hwy Po Box188 Malad City, Idaho 83252 Tel 208.766.2206

TAPEL WILLAMETTE LTD. S.A.

Av. Estero La Posada 3625 Parque Industrial Coronel Coronel, Chile Tel 011.56.412.928.100 www.tapel.cl



Revision Date June 2012

DISCLAIMER OF WARRANTY

TEST RESULTS ARE TO BE CONSIDERED AS REPRESENTATIVE OF CURRENT PRODUCTION AND SHOULD NOT BE TREATED AS SPECIFICATIONS. WHILE ALL THE INFORMATION PRESENTED IN THIS DOCUMENT IS BELIEVED TO BE RELIABLE AND TO REPRESENT THE BEST AVAILABLE DATA ON THESE PRODUCTS, NO GUARANTEE, WARRANTY, OR REPRESENTATION IS MADE, INTENDED, OR IMPLIED AS TO THE CORRECTNESS OR SUFFICIENCY OF ANY INFORMATION, OR AS TO THE SUITABILITY OF ANY CHEMICAL COMPOUNDS FOR ANY PARTICULAR USE, OR THAT ANY CHEMICAL COMPOUNDS OR USE THEREOF ARE NOT SUBJECT TO A CLAIM BY A THIRD PARTY OR INFRINGEMENT OF ANY PATENT OR OTHER INTELLECTUAL PROPERTY RIGHT. EACH USER SHOULD CONDUCT A SUFFICIENT INVESTIGATION TO ESTABLISH THE SUITABILITY OF ANY PRODUCT FOR ITS INTENDED USE.

USER SHOULD CONDUCT A SUFFICIENT INVESTIGATION TO ESTABLISH THE SUITABILITY OF ANY PRODUCT FOR ITS INTENDED USE.
PROPER APPLICATION IS THE RESPONSIBILITY OF THE USER. AS WITH ANY PRODUCT THE USE OF THE THIS PRODUCT IN A GIVEN APPLICATION MUST BE TESTED (INCLUDING BUT NOT LIMITED TO FIELD TESTING) IN ADVANCE BY THE USER TO DETERMINE SUITIBILITY. TESTING IS THE REQUIREMENT OF BOTH ENGINEERS AND CONTRACTORS ALIKE. WVCO DOES NOT WARRANT THE APPLICATION UNDER ANY OR ALL CIRCUMSTANCES.