

## Application Instructions PS-COATING









Read SAFETY DATA SHEET before handling or applying Always wear appropriate PPE during handling and application

## FOR BEST RESULTS:

Store and handle cartridges upright (60-90°F, 15-32°C)

Condition cartridges to ≥60°F (15°C) before using.

Use with SULZER MixCoat<sup>™</sup> 1500 series applicator and air compressor capable of 12CFM @100psi

- 1. Remove nut and cap.
- 2. Secure static mix-tube with spray nozzle to cartridge and tighten nut.
- 3. Load cartridge into dispenser (snaps into place), keep upright.
- 4. Connect air supply line to applicator.
- 5. Connect atomizing air line to spray nozzle
- 6. Purge any air in cartridge by spraying with cartridge upright.
- 7. Spray initial portion outside application area while adjusting material flow rate (A) and atomizing air pressure (B) to desired levels.
- 8. Apply continuously with smooth, even passes. Do not trigger on and off.



7.A.



